



MTA

Pre Purchase Inspection

Reference: RB 60521 **Examiners ID:** MM
Date: 18/01/2009
Time: 14.30
Inspection Type: Mobile Inspection \$244.00 inc GST

Special instructions:

Customer Details:

Name: Exxxx Pxxxxxxxxxl
Title: Ms
Company:
Address:
City:
Telephone:
Mobile: 04xxxxxxxx
Email: xxxxxxxxxxx@gmail.com

Contact Details:

Name: Bxxxxt
Title: Mr
Company:
Address: xxxxx xxxxxxxxxxx
City: Lxxxxd
Telephone:
Mobile: 041xxxxxxxx
Email:

Vehicle Details:

Make: Hyundai **Registration:** xxx 000
Year: 1999 **Vin#:** xxxxxxxx1234TY
Model: XL **Registration Date:** XX/XX/09
Colour: Blue **Odometer:** 132307

Thank you for having your vehicle inspected by an accredited Motor Traders Association of NSW Inspection Centre.

Due to the complexity of some vehicle systems and in order to provide you with an inspection at a competitive price, please make sure you read the following. If you have any questions please ask your MTA Accredited Vehicle Examiner or phone the MTA Inspections on 1300 682 123

1. The pre-purchase inspection is largely a visual and/or check operation inspection. It is not practical to dismantle every item on the vehicle.
2. This inspection does not check the compression of the engine
3. Airbags (SRS) is a complicated electronic system that requires complex and involved testing procedures. An MTA Pre-purchase inspection checks the operation of the system check light and reports accordingly. This inspection makes no guarantee that the system will or will not work as the manufacturer intended.
4. Anti-Lock Braking System (ABS) also has complex testing procedures. This inspection checks the system check light is operating and reports accordingly. This report offers no guarantee that the ABS will continue to work indefinitely.
5. This inspection is not a substitute for a "Pink Slip" inspection
6. This inspection is prepared for the person named on the report and no warranty is offered or provided to any third party.
7. This report may indicate a problem but not provide any further information about this problem; this is because further dismantling may be required to provide an accurate diagnosis.
8. This report is not to be relied upon to determine if internal problems exist in the engine, transmission or any other operational component; general operation checks are carried out only.

This is a visual inspection only and no component has been removed as a result
There will be no warranties or guarantees given to the limit of inspection on this vehicle by the
MTA Pre Purchase Inspections

Inspection report

Overall Mechanical Condition:

Fair

Overall Panel Condition:

Poor

Service Records up to date:

No

Overall Comments and Notes

Excellent	9 - 10
Good	7 - 8
Fair	5 - 6
Poor	3 - 4
Bad	0 - 2

Mechanical wear is considered to be normal for kilometres travelled. However slight engine noise is evident at low rpm. Vehicle has had unsatisfactory paint and panel repairs in various areas.,
 Vehicle has rust spots on boot lid

ROAD TEST

This road test took place under the following conditions:

Tested at speeds up to:

60

Road Conditions:

Dry

Comments:

Vehicle functioned with no major faults evident at time of test drive

Overall Roadtest Condition:

Good

INTERIOR

Items checked (If fitted):

ABS Warning Light	Electric Window - Passenger Side Rear	Seat - Rear Passenger Side
Additional Seating	Electric Window - Drivers Side Front	Seat Belt Driver
Aftermarket Sport Gauges	Electric Window - Drivers Side Rear	Seat Belt Front Centre
Air conditioning	Electric Windows	Seat Belt Front Passenger
Brake Pedal	Fan	Seat Belt Rear Centre
Central Locking	Front Door Lock - Passenger Side	Seat Belt Rear Passenger
Centre Console	Front Door Lock - Drivers Side	Seat Belt Rear Drivers Side
Cigarette Lighter	Glove Box	Seat Covers
Dashboard	Handbrake	Seat Covers - Front
Door Ajar Warning Light	Heater	Seat Covers - Rear
Door Handle - Passenger Side Front	Fuel Gauge	Sound Equipment
Door Handle - Passenger Side Rear	Horn	SRS Warning Light
Door Handle - Drivers Side Front	Ignition barrel	Starter Inhibitor Switch
Door Handle - Drivers Side Rear	Instrument Panel Lights	Steering Wheel
Door Rubber - Passenger Side Front	Interior Boot Release	Trim
Door Rubber - Passenger Side Rear	Interior Door/Filter Controls	Trim (Doors)
Door Rubber - Drivers Side Front	Interior Fuel Filler Release	Washer
Door Rubber - Drivers Side Rear	Interior lights	
Door Rubber - Rear	Lighter	
Door Rubbers	Map Reading Lights - Interior	
Door Trim - Passenger Side Front	Phone Kit Holes	
Door Trim - Passenger Side Rear	Phone Kit/Other Accessory	
Door Trim - Drivers Side Front	Seat - Driver	
Door Trim - Drivers Side Rear	Seat - Front	
Door Trim - Rear	Seat - Front Centre	
Driver controls	Seat - Front Passenger	
Driver Gauges	Seat - Rear	
Electric Window - Passenger Side Front	Seat - Rear Centre	

Notes:

crack in dash board
 Burn marks on rear seat various areas.
 General wear was evident in carpet, seats and interior trim
 Minor detailing is required.

Overall Interior Condition: Good

ELECTRICAL SYSTEM

Items checked (If fitted):

Battery	High Tension Leads	Tail Lights - Drivers Side
Battery Cables	Instrument Panel Lights	Terminals (Corrosion)
Battery Terminals	Interior lights	Indicator - Front Passenger Side
Brake Lights	Map Reading Lights - Interior	Indicator - Front Drivers Side
Fog Light - Passenger Side	Number Plate Lights	Indicator - Rear Passenger Side
Fog Light - Drivers Side	Parking Lights - Operation	Indicator - Rear Drivers Side
Fuel Gauge	Sound Equipment	
Headlights - Passenger Side	SRS Warning Light	
Headlights -Drivers Side	Tail Lights - Passenger Side	

Notes:

The electrical system is in good working order

Overall Electrical Condition:

Good

ENGINE

Items checked (If fitted):

Accessories Belt	Engine Seal - Front Main	Manifold - Inlet
Emission Controls	Engine Seal - Rear Main	Oil
Engine Mount - Near Side	External part of engine	Oil Level
Engine Mount - Off Side	Fan	Serpentine Belt
Engine Mount - Other	Front region of engine	Turbo/Intercooler
Engine Mount - Rear	Rocker Cover Gasket	
Sump	Turbo	
Sump region	Loose or Defective Drive Belt	

Notes:

Slight engine noise was evident at low rpm
 Minor oil seepage at sump area and rocker cover gasket


Overall Engine Condition:

Fair

BODY

Items checked (If fitted):

- | | |
|----------------------------------|--------------------------------|
| Bonnet | Hub Cap - Passenger Side |
| Boot Lid | Hub Cap - Passenger Side Rear |
| C Pillar - Passenger Side | Hub Cap - Drivers Side |
| C Pillar - Drivers Side | Hub Cap - Drivers Side Rear |
| Chassis | Mounting points under car |
| Chassis - Passenger Side | Near Side A Pillar |
| Chassis - Drivers Side | Near Side B Pillar |
| D Pillar - Passenger Side | Off Side A Pillar |
| D Pillar - Drivers Side | Off Side B Pillar |
| Door - Passenger Side | Quarter Panel - Passenger Side |
| Door - Passenger Side | Quarter Panel - Drivers Side |
| Door - Drivers Side | Rear Bumper |
| Door - Drivers Side | Spoiler/Body Kit |
| Door Handle - Passenger Side | Turret |
| Door Handle - Passenger Side | Window - Passenger Side |
| Door Handle - Drivers Side | Window - Passenger Side Rear |
| Door Handle - Drivers Side | Window - Drivers Side Front |
| Front Bumper | Window - Drivers Side |
| Front Door Lock - Passenger Side | Wiper - Blades |
| Front Door Lock - Drivers Side | Wiper - Operation of Arms |
| Guard - Passenger Side | Front Windscreen |
| Guard - Drivers Side | Rear Window Glass |



Notes:

Rust is evident on boot lid
 Scratches, stone chips and minor carpark indentations are evident in various areas.
 Poor paint and panel repairs are evident in various areas.
 Condition of paint is poor

Vehicle Cleanliness:	Fair
Overall Body Condition:	Poor

COOLING SYSTEM

Items checked (If fitted):

Air conditioning	Radiator Hose
Coolant	Radiator Hose - By-Pass
Fan	Radiator Hose - Heater
Heater	Radiator Hose - Lower
Heater Core	Radiator Hose - Upper
Heater Tap	Thermostat Fan
Radiator	Water Pump

Notes:

The cooling system is in good condition with no leaks or perished hoses

Overall Cooling System Condition:

Good

EXHAUST

Items checked (If fitted):

Catalytic Converter	Exhaust Pipe
Centre Exhaust	Manifold - Exhaust
Exhaust	Modified Exhaust System
Exhaust - Rear	Muffler Box Rear
Exhaust Front	Tail Pipe

Notes:

The exhaust is in good condition with no signs of rust or leaking

Overall Exhaust System Condition:

Good

BRAKING SYSTEM

Items checked (If fitted):

ABS	Brake Hoses
ABS Warning Light	Brake Master Cylinder
Brake Booster	Handbrake
Brake Fluid	Security of components

Notes:

The braking system appears in good order
 Brakes operated with no faults evident at time of inspection. However brake pads; linings; discs; drums and other internal brake components may require replacing as part of normal servicing.

Overall Braking System Condition:

Good

FUEL SYSTEM

Items checked (If fitted):

		LPG Vehicles	
Carburetor	Fuel Line	Filler Cap and retaining strap	Switching gas/petrol
Emission Controls	Fuel Pump	Energiser ring and thread	Gas guage operation
Fuel Cap	Fuel Rail	Tank security	
Fuel Filter	Fuel Tank	Tank heat sheild/stone guard	
Fuel Gauge	Injector	LPG lines secure 600mm intervals	
Fuel Hoses		wiring fixed correctly	

Notes:

The Fuel system has no faults and is in good condition

Fuel System Type:

Unleaded

Overall Fuel System Condition:

Good

STEERING AND SUSPENSION

Items checked (If fitted):

Ball Joint - Lower	Steering column
Ball Joint - Upper	Steering Wheel Free-Play
Bushes	Sway Bar Bushes Front
Control Arm - Bushes Rear	Sway Bar Bushes Rear
Control Arm - Rear Lower	Sway Bars
Control Arm - Rear Upper	Tie Rod End - Passenger Side
Front Control Arm - Lower	Tie Rod End - Drivers Side
Front Control Arm - Upper	Torsion Bar Front
Front Control Arm Bushes	Tyre - Passenger Side Front
Independent Rear Suspension Arm	Tyre - Passenger Side Rear
Pan-Hard Rod Bushes	Tyre - Drivers Side Front
Power Steering	Tyre - Drivers Side Rear
Power Steering Hoses	Tyre - Spare
Power Steering Lines	Vehicle Height
Power Steering Pump	Wheel - Passenger Side Front
Rack & Pinion	Wheel - Passenger Side Rear
Shackle Bushes Front	Wheel - Drivers Side Front
Shackle Bushes Rear	Wheel - Drivers Side Rear
Shocks - Front	Wheel - Spare
Shocks - Rear	Wheel Bearings - Front
Steering	Wheel Bearings - Rear
Steering Box	

Notes:

Wear was evident in steering and suspension considered to be indicative to kilometres travelled
Repairs and maintenance must be expected.

Overall Steering and Suspension Condition: Good

TRANSMISSION

Items checked (If fitted):

Automatic Transmission	Hydraulic Clutch
Centre Bearing	Manual Transmission
Clutch	Oil
Clutch Cable	Oil Level
Clutch Fluid	Starter Inhibitor Switch
Clutch Master Cylinder	Tail Shaft
Clutch Operation	Transfer Case
Clutch Pedal	Transmission
Clutch Slave Cylinder	Transmission - Fluid
CV Joint - Front Inner Near Side	Transmission - Mounts
CV Joint - Front Inner Off Side	Transmission - Seal
CV Joint - Front Outer Near Side	Transmission - Select Gears
CV Joint - Front Outer Off Side	Transmission Hose
Differential - Rear Wheel Drive	Universal Joint - Front
Driveline	Universal Joint - Rear

Notes:

Clutch and transmission functioned with no faults evident at time of inspection. However, due to kilometres travelled, however, due to kilometres travelled, servicing and repairs must be expected.

Overall Transmission Condition: Good

UNDERSTRUCTURE

Items checked (If fitted):

Chassis Passenger Side	Chassis - Off side
Chassis Drivers Side	Mounting points under car

Notes:

The understructure of the vehicle is in good order.

Overall Understructure Condition: Excellent